



Setup



SET UP SURFACE FOR MOUNTING

Measure and mark desired centre-point using tape measure and spirit level.

Determine drill points by measuring half the Centre-To-Centre value from the centre-point and marking with pencil.



Installation



INSTALLING HARDWARE ON SURFACE

1. Drill holes as required at marked points, keeping the drill bit perpendicular to the mounting surface at all times.

NOTE: ALWAYS start drilling from the outer/front surface that the product will sit on.

2. Use supplied hardware to fix product to surface. Ensure not to overtighten as this may result in damage to the mounting material.